Travertine Floor Holes

Authored by: **Jeremy & Katy Wilcock** [jeremy@wilcock8696.freeserve.co.uk] Saved From: https://marblecleaning.org/knowledgebase/article.php?id=104

We have recently moved into a new house with a travertine floor in the kitchen. Recently we have noticed pin holes appearing in the floor which then crumble to 2.5-3.5cm across. The floor has been sealed & we have underefloor heating. The flooring contractor have advised that these holes can be filled & the floor treated with a chemical hardener called "SK40" which will help stabilise & Harden the floor tile. I would be most grateful if you could give your opinion on this course of action because we are unsure how effective it will be. Thank You

Katy & Jeremy