color enhancer on ubatuba

Authored by: Maurizio Bertoli [mail@mbstone.com]

Saved From: https://marblecleaning.org/knowledgebase/article.php?id=1054

A week ago I had a new granite vanity top {uba Tuba} installed. At the time of installation it was sealed by the Co. that installed it. To me it appears to have a haze under the surface. The merchant told me that I should use Pledge to obtain a deeper color. It does make the color deeper and shiny, but its only a temporary fix. Could I use your color enhancer? Do you have a product to remove the sealer[Stonetech Heavy Duty Sealer] they put on it so I can use your product? Thank You Rein Smit

Dear Rein:

" At the time of installation it was sealed by the Co. that installed it. ―

No, they did not. To make sure, they did smear some totally useless (under the circumstances) impregnating sealer, but that does not mean that they actually sealed your stone. Nobody can seal charnockite (Ubatuba): it is too darn dense to take any impregnator in.

That said, you're obviously dealing with some residue of their impregnator that was not thoroughly removed from the surface of the stone.

I can anticipate you that it is not going to be easy to strip it off, for it involves a potent paint stripper based on Methylene Chloride (available at any hardware stores) that you could not pay me enough to use. Not to mention that if for any chance that slab had been resined by the factory (like many slabs of Ubatuba are these days) that chemical could irreversibly damage the resin near the surface of the stone.

The ideal it would be to strip it professionally with a "hot― polishing powder for marble by implementing the so-called "dry-polishing― method.

In conclusion, demand your fabricator to come back and deal with their own mess; and, once they're done with it, tell them to go "seal― their sisters' Ubatuba.

Trying to strip at least some of the sealer that they have in their brains, so that some real stone intelligence had a chance to sink in, would be beneficial, too. J

I can finally anticipate to you that MB-6 wouldn't work, for the very reason that an impregnator couldn't: the stone is inherently too dense to absorb anything, and MB-6, like any other impregnator, is also a below-the-surface (of the stone) type of products. Not to mention that a product like MB-6 is not meant to produce any shine. Stone is polished mechanically by abrasion and friction – like gemstone – not by applying some sealer on it.

www.marblecleaning.org â€" The only Consumers' Portal to the Stone Industry Establishment!