Travertine Install possible weird situation

Authored by: Maurizio Bertoli [mail@mbstone.com]

Saved From: https://marblecleaning.org/knowledgebase/article.php?id=1263

We recently had travertine, honed and not filled installed throughout a laundry, hall and bath area. We elected to get a little nutty and have the entire shower pan, walls and ceiling done in the travertine as well. Tonight I had a builder friend of mine stop by only to tell me I had royally screwed up with that shower install and was headed for disaster. The installer used a sanded grout and the pattern versaille, has very large tiles that are also on the ceiling. I had inquired at the shop where I bought the tile if the ceiling tiles would be a problem and they had said no. Can you give me any good news tonight or am I looking at a bigger problem down the road?

Kimberly:

Your information is too sketchy. The use of sanded grout alone is not a problem. It depends what kind of grout gap he left in between tiles.

Very definitely, you will not have a problem with the tiles in the ceiling of the stall, unless they are not bond well and eventually fall down. But it has nothing to do with the pattern of the grout.

And remember, every single penny of the cost of the literature will be used to support this site and its cause: **your** cause.

While you are in the "Helpful Hints― section, do spend some time reading all of the interesting FREE articles you'll find in there!

Finally, keep in mind that we need your support to help us helping you!

Will you please read and e-sign our Statement of Purpose at: http://www.marblecleaning.org/purpose.htm?

By spreading the word about this valuable site among your friend & family and the stone trades' people you've been dealing with, you will be rendering everybody a valuable service!

Thank	you

Ciao and good luck,

Maurizio Bertoli

www.marblecleaning.org â€" The only Consumers' Portal to the Stone Industry Establishment!