

Crema Polished Marble Vanity Top - GE Silicone

Authored by: **Stu Rosen** [mailto:mail@stoneshine.com]

Saved From: <https://marblecleaning.org/knowledgebase/article.php?id=1797>

Q.While setting the counter backsplash, some GE Silicone Caulk came in contact w/the vanity top. I must of tried cleaning it up w/a damp cloth. The top appear etched & may still have silicone in the etched areas. How can it be cleaned & retored to a polished finish? Thanks, Al

A.Hi, Al I dont think the silicone etched the stone anything is possible.You didnt mention what stone you have. You could try our mb-11 "happiness in a bottle". Ofcourse if that doesnt work you will need the services of a bone fide stone resfinisher which can be found at this website.

www.stoneandtilepros.com

Stu Rosen

www.mbstone.com.

www.stoneshine.com